



AUDI Q3 Sportback: 2BWE200

Vinnnummer:	WAUZZZF36N1105997	Versionname:	Q3 Sportback 35 TFSI S tronic Bus. Ed. Attraction (Mild Hybrid) 110kW/150pk 5D/P Auto-7
First Registrationdate:	14/04/2022	Fiscalpower:	
Expertise Mileage:	171531	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c609
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

235/55/18/104 H				
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/55 R 18 104 H
Tyre size FR				235/55 R 18 104 H
Tyre size RL				235/55 R 18 100 H
Tyre size RR				235/55 R 18 100 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit

Yes Compressor

Yes

Number of charging cables (normal)

0

Number of charging cables (rapid charge)

0

Grille, Broken, Replace



Bumper spoiler F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Door FL, Scratch(es), Polish



Door trim RL, Scratch(es), Smart repair





Boot lid covering R, Scratch(es), Acceptable



Rear light R tailgate, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable

