



CITROEN C5 Aircross: 1YXW130

Vinnnumber:	VR7ARHNSKLL089757	Versionname:	C5 Aircross 1.2 PureTech 130 S/S MAN6 Feel
First Registrationdate:	26/01/2021	Fiscalpower:	96kW/131pk 5D/P Man-6
Expertise Mileage:	62607	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	N/A
Transmission:	Front	Parking lot:	b105
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	N/A		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

225/55/18/102 V				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		




Bumper F, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Wheel arch cover FL, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Replace



Door RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Door FR, Scratch(es), Repair and paint (complete)



Wheel arch cover FR, Scratch(es), Smart repair



Wing FR, Scratch(es), Acceptable



Door FR, Bad repair, Check



Wing trim RR, Scratch(es), Smart repair



Roof, Dent(s) and scratch(es), Repair and paint (complete)

