Print

MACADAM

BMW 2 GRAN COUPÉ: 2AAZ334

Vinnumber:	**WBA11AK0407H76434**	Versionname:	**218iA (100kW)**
First Registrationdate:	**4/02/2021**	Fiscalpower:	
Expertise Mileage:	**71980**	Power Kw:	**100**
Bodytype:		Body colour	**Dark Grey**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:		Parking lot	**3214**
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**18000.0**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	**No Tow bar**
Radio multimedia			
Type of headlighting	**Headlighting LED**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining semi-Alcantara**		
Type of climate control	**Autom climate control**		
Sport seats			
Type of GPS storage	**HD**		

Limited Technical Inspection

Degree of wear

Summer tyres:	**255/50/19/103 T**			
	Fr.L.	**Vredestein: 6 mm**	Fr.R.	**Vredestein: 6,1 mm**
	Re.L.	**Vredestein: 5 mm**	Re.R.	**Vredestein: 4,2 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.1**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.2**
Tyre size FL	**255/50 R 19 103 T**
Tyre size FR	**255/50 R 19 103 T**
Tyre size RL	**255/50 R 19 103 T**
Tyre size RR	**225/40 ZR 18 92 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2480**
Tyre make RR	**2480**

Assistance equipment

Number of charging cables (normal)	**0**	Runflat	**No**
Number of charging cables (rapid charge)	**0**		

Total cost ex VAT	2021,40
Seat cover FR, Stain, Cleaning	28,43

Bonnet, Scratch(es), Acceptable	0,00

Bumper F, Scratch(es), Repair and paint (complete)	289,07

Bumper moulding F, Scratch(es), Replace	132,30

Alloy rim FL polished, Scratch(es), Repair and paint (complete)	199,04

Alloy rim RL polished, Scratch(es), Repair and paint (complete)	199,04

Wing FL, Deformed / Strained, Repair and paint (complete)	346,91

Door FL, Scratch(es), Acceptable	0,00

Door RL, Dent(s), Acceptable	0,00

Tyre repair kit, Missing, Check	0,00

Bumper R, Dent(s) and scratch(es), Repair and paint (complete)	335,47

Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04

Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04

Outside rear-view mirror base R, Scratch(es), Acceptable	0,00

Door RR, Scratch(es), Acceptable	0,00

Door FR, Scratch(es), Acceptable	0,00

Roof, Dent(s), Paintless dent repair	93,06

MACADAM